



Safety+Health

The Official Magazine of the NSC Congress & Expo

safetyandhealthmagazine.com/articles/16281-manufacturer-issues-recall-for-mounting-brackets-on-aerial-lifts



Photo: Genie Industries

Manufacturer issues recall for mounting brackets on aerial lifts

October 18, 2017

Redmond, WA – Lifting and material handling manufacturer [Genie Industries](http://www.genielift.com) has issued a [safety recall](#) for certain aerial lifts, stating that some mounting brackets on the

Operator's Protective Alarm may loosen and possibly fall from the machine, creating a collision hazard.

A possible 81 devices have been affected across various S-Boom and Z-Boom models. Affected users are directed to order replacement parts through the Genie website, by phone at (800) 536-1800 or by fax at (888) 274-6192. For silver mounting brackets, the kit part number is 1275550GT. For black mounting brackets, the kit part number is 1277210GT.